

TO 1.

- 2. CHECK CLEARANCE OF PRESSURE PLATE WITH FILTER HOUSING ON TRACKER S/N 9.
- RESULTS OF MEN 6035 SHOWED THAT THE CLEARANCE WAS NOT SUFFICIENT AND CAUSED SOME FORMAT SHIFTING AND BANDING.
  - THE CLEARANCE SHOULD BE .018.

END OF NESSAGE

25 YEAR RE-REVIEW

SECRET

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.